UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,872,867 B1

Page 1 of 1

DATED : March 29, 2005 INVENTOR(S) : John J. Senetar

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 20,

Lines 12-13, after "gas inlet," delete "where the process in an MTO process and that feed contains methanol".

Line 14, after "gas outlet," insert -- where the process is an MTO process and the feed contains methanol --.

Signed and Sealed this

Thirty-first Day of May, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office